

315 BG Low Viscosity Full Synthetic ATF

APPLICATION CHART

BG Low Viscosity Full Synthetic ATF, PN 315, meets or exceeds the performance requirements of the following automatic transmission fluids.

MAKE	ATF PN
Acura	DW-1, TYPE 3.0 08200-9016A, TYPE 3.1 08200-9017A
Aisin Warner	AW-1
Audi	G 052 540, G 055 005, G 055 162, G 060 162
BMW	83 22 0 142 516, 83 22 2 152 426, 83 22 2 305 396, 83 22 2 355 599, 83 22 2 289 720, 83 22 0 397 114, 83 22 2 163 514, 83 22 2 220 445, 83 22 0 024 359, 83 22 0 403 249
Chrysler/Mopar	68157995AA, 68157995AB, 68218925AA, 68171866AA, 68171866AB, 68171869AA, 68171869AB
DSIH	6P805 (GEELY, SSANGYONG, MAHINDRA 6SP)
Ford	MERCON®LV
GM	DEXRON®-VI, 88863400, 88863401
Honda	DW-1, TYPE 3.0 08200-9016A, TYPE 3.1 08200-9017A
Hyundai/Kia	SP-IV, SPH-IV, SP-IV-RR, NWS-9638, 040000C90SG, SP4-M
Isuzu	SCS 2-90531-200-0
Jaguar	JDE 26444, C2C8432
JASO	1-A-LV
JWS	3324
Land Rover	JDE 26444, LR 023288, LR 023289, TYK500050
Lexus	WS
Mazda	ATF-FZ (0000-FZ-113E-01)
Mercedes-Benz	236.12, 236.14, 236.15, 236.16, 236.17, 236.41
Mitsubishi	ATF-J3, ATF-PA, SP-IV
Nissan	MATIC-S
Porsche	000 043 306 24, 958 300 540 00
Shell	M-L12108, 3353, M-1375.4, M-1375.6
Toyota	WS (JWS 3324)
Volvo	31256774, 31256775
VW	G 052 540, G 055 005, G 055 162, G 060 162
ZF Friedrichshafen AG	LifeGuard Fluid 6 (S671090255), LifeGuard Fluid 6 Plus (S671090281), LifeGuard Fluid 8 (AA00601304, S671090312)

BG Low Viscosity Full Synthetic ATF is not recommended for use in the following applications:

- Ford Type F, Ford MERCON® ULV, XT-12-QULV
- Continuously Variable Transmissions (CVTs)
- Dual Clutch Transmissions (DCT)
- Direct-Shift Gearbox (DSG)
- GM DEXRON®-HP

BG Products, Inc., accepts no liability for excessive use or misuse of this product.

Revision date 11-30-18

Revisions **Added to Porsche section**
- 000 043 306 24, 958 300 540 00

10-12-18 **Added to Acura:**
-DW-1, TYPE 3.0 08200-9016A

Added to BMW:
-83 22 2 305 396, 83 22 2 355 599, 83 22 2 289 720, 83 22 0 397 114, 83 22 2 163 514,
83 22 2 220 445, 83 22 0 024 359, 83 22 0 403 249

Added to Chrysler/Mopar:
-68218925AA, 68171866AA, 68171866AB, 68171869AA, 68171869AB

Added to GM:
-88863400, 88863401

Added to Honda:
-TYPE 3.0 08200-9016A, TYPE 3.1 08200-9017A

Added to Hyundai/KIA:
-040000C90SG, SP4-M

Added Isuzu:
-SCS 2-90531-200-0

Added Jaguar:
-C2C8432

Added to Land Rover:
-LR 023288, LR 023289, TYK500050

Added Mazda:
-ATF-FZ (0000-FZ-113E-01)

Added Mercedes-Benz:
-236.15, 236.16, 236.17

Changed on Volvo:
- WAS "31256675" UPDATED TO "31256775"

10-12-18 Added to Not Recommended section

- GM DEXRON®-HP

Removed from Not Recommended section

- All Mercedes Benz 722.9 transmissions built after June 21, 2010 requiring ATF A0019897803 (236.15)

9-14-17 Added to Not Recommended section

- Ford MERCON® ULV, XT-12-QULV

12-9-16 Fixed on Ford:

REMOVED SPACE BETWEEN MERCON® AND LV

10-20-16 Added to Acura:

-TYPE 3.1 08200-9017A

11-2-15 Original